

STEMCO Hub Cap Part Number Obsolescence

This bulletin serves as a formal notice that STEMCO has decided to discontinue several part numbers within our Hub Cap product line to improve operational efficiency. Effective immediately, the following part numbers will no longer be available for purchase.

For more information, please contact your STEMCO representative or visit Stemco.com



Discontinued Part Numbers
340-4054
340-4054-03
340-4341
345-4341
356-4054-03

Thank you for your continued support of STEMCO. Please update your system to reflect this change.