

STEMCO Hub Seal Part Number Obsolescence

This bulletin serves as a formal notice that STEMCO has decided to discontinue the sale of select Hub Seals. Effective immediately, the following Hub Seal part numbers will no longer be available for purchase but we will fulfill existing orders in our system.

Obsolete part numbers:

- 309-0960
- 309-0965
- 309-0970
- 392-9018
- 392-9035

Additionally, the following Hub Seal part numbers will no longer be available and we will not fulfill existing orders in our system.

Obsolete part numbers:

- 392-9007
- 320-2077
- 309-0957
- 309-0915
- 308-0856

For more information, please contact your STEMCO representative or visit Stemco.com

Thank you for your continued support of STEMCO. Please update your system to reflect this change.