

## Warranty and Replacement Parts Available for Aeris® and AirBAT®

To: All Distributors of STEMCO Aeris® and AirBAT® Products

STEMCO, an EnPro Industries company, has made the difficult decision to discontinue production of the Aeris® tire inflation system and the AirBAT® tire pressure monitoring system. However, STEMCO will continue to maintain a supply of replacement parts available for order for a limited time for replacement / warranty needs. Due to the parts numbers being discontinued, they will be non-returnable.

Part Number	Description	Part Number	Description
831-0248	Aeris SmartSense Control Box, 4-Port	831-0224	Dual Tire, P-Spindle, Grease, 358-4195 Integrated Sentinel Hubcap Pkg.
831-0249	Aeris SmartSense Control Box, 2-Port	831-0312	Single Tire, N-Spindle, Oil, 356-4009 Integrated Sentinel Hubcap Pkg for Aeris Hendrickson Tiremaxx adaptation
831-0246	Aeris SmartSense Control Box, 4-Port Omnitrac Interface	831-0412	Dual Tire, N-Spindle, Oil, 356-4009 Integrated Sentinel Hubcap Pkg. for Aeris Hendrickson Tiremaxx adaptation
831-0245	Aeris Mechanical Control Box	831-0314	Single Tire, N-Spindle, Grease, 358-4009 Integrated Sentinel Hubcap Pkg. for Aeris Hendrickson Tiremaxx adaptation
831-0250	Aeris SmartSense Driver Warning Lamp, Dual Axle	831-0414	Dual Tire, N-Spindle, Grease, 358-4009 Integrated Sentinel Hubcap Pkg. for Aeris Hendrickson Tiremaxx adaptation
831-0251	Aeris SmartSense Driver Warning Lamp, Single Axle	831-0322	Single Tire, P-Spindle, Oil, 356-4195 Integrated Sentinel Hubcap Pkg. for Aeris Hendrickson Tiremaxx adaptation
831-0260	Aeris ABS Adaptor	831-0422	Dual Tire, P-Spindle, Oil, 356-4195 Integrated Sentinel Hubcap Pkg. for Aeris Hendrickson Tiremaxx adaptation
831-0035	Pressure Protection Valve, Replacement	831-0324	Single Tire, P-Spindle, Grease, 358-4195 Integrated Sentinel Hubcap Pkg. for Aeris Hendrickson Tiremaxx adaptation
831-0049	Axle Plug (N-Spindle, 1.75" ID)	831-0424	Dual Tire, P-Spindle, Grease, 358-4195 Integrated Sentinel Hubcap Pkg. for Aeris Hendrickson Tiremaxx adaptation
831-0048	Axle Plug (P-Spindle, 2.75" ID)	810-0051	Replacement Hose, 19.5/22.5 Wheel Str
831-0188	Dual Duckbill Vent, 1/8 NPT	810-0052	Replacement Hose, 17.5 Wheel, 180
831-0111	Single Tire, N-Spindle, Oil, 340-4009 Hubcap Pkg.	810-0053	Replace Hose, 19.5/22.5 Wheel, 180
831-0211	Dual Tire, N-Spindle, Oil, 340-4009 Hubcap Pkg.	810-0054	Replace Hose, 24.5" 180 D
831-0112	Single Tire, N-Spindle, Oil, 356-4009 Integrated Sentinel Hubcap Pkg.	810-0055	Replace Hose, 24.5 Wheel, Straight
831-0212	Dual Tire, N-Spindle, Oil, 356-4009 Integrated Sentinel Hubcap Pkg.	831-0034	Pressure Protection Valve, Replacement
831-0113	Single Tire, N-Spindle, Grease, 342-4009 Hubcap Pkg.	831-0133	Ss Dwl & Bracket Assembly Vg Trailer
831-0213	Dual Tire, N-Spindle, Grease, 342-4009 Hubcap Pkg.	814-0090*	Steer Tire AirBAT set to 90 PSI
831-0114	Single Tire, N-Spindle, Grease, 358-4009 Integrated Sentinel Hubcap Pkg.	815-0090*	Single Tire AirBAT set to 90 PSI
831-0214	Dual Tire, N-Spindle, Grease, 358-4009 Integrated Sentinel Hubcap Pkg.	816-0090*	Dual Tire AirBAT set to 90 PSI
831-0121	Single Tire, P-Spindle, Oil, 340-4195 Hubcap Pkg.	850-0009*	Bracket, AirBAT, Hub Pilot
831-0221	Dual Tire, P-Spindle, Oil, 340-4195 Hubcap Pkg.	850-0022*	Bracket, SST, Sitre-Tag, Hub Pilot
831-0122	Single Tire, P-Spindle, Oil, 356-4195 Integrated Sentinel Hubcap Pkg.	820-8000*	Driver Alert System
831-0222	Dual Tire, P-Spindle, Oil, 356-4195 Integrated Sentinel Hubcap Pkg.		
831-0123	Single Tire, P-Spindle, Grease, 342-4195 Hubcap Pkg.		
831-0223	Dual Tire, P-Spindle, Grease, 342-4195 Hubcap Pkg.		
831-0124	Single Tire, P-Spindle, Grease, 358-4195 Integrated Sentinel Hubcap Pkg.		

\*Must process through warranty.

To send AirBAT Sensors and Aeris to warranty for consideration, ship via prepaid freight to:

ATTN: WARRANTY DEPARTMENT  
 STEMCO  
 300 Industrial Drive  
 Longview, TX 75602

Thank you for your continued support of STEMCO.