

## STEMCO Defender Hub Cap Part Number Obsolescence

This bulletin serves as a formal notice that STEMCO has decided to discontinue several part numbers within our STEMCO Defender Hub Cap product line for a purchase quantity of one each. These part numbers will remain active for purchase of quantities 25. Effective immediately, the following part numbers will be affected.

For more information, please contact your STEMCO representative or visit [Stemco.com](http://Stemco.com)



Obsolete Part Numbers	Active Part Numbers
361-4009	360-4009
361-4024	360-4024
361-4195	360-4195
364-4009	363-4009
364-4024	363-4024
364-4195	363-4195
364-5109	363-5109
364-5124	363-5124
364-5209	363-5209
364-5224	363-5224
367-4009	366-4009
367-4024	366-4024
367-4195	366-4195
369-4009	368-4009
369-4024	368-4024
369-4195	368-4195

Thank you for your continued support of STEMCO. Please update your system to reflect this change.